

nice choice  
of words. ☺

August 13, 2005

Notes to file:

ref. Items to consider re three worship services.

- Acoustics in Room 300

There will be a problem with classes in Room 300 A and B which are directly over Room 100. It is important that activities in Room 100 be kept under control

We inserted a noise-reduction layer in the floor of Room 300, but it does little to eliminate the noise coming from Room 100. It will be necessary to look into this problem in the future, but correction will not be quick, easy or cheap. For now, only help from those in Room 100 will help with the problem.

- Sanctuary seating is difficult to estimate because seat width is not defined.

<u>Seat width</u>	<u>Seating capacity</u>
18 in. (code)	484
21 in. (actual estimate)	<u>442</u>
Average	463 x 80%
Reasonable capacity	<u>370</u>

- The Facilities Team talked about who might be the Parking Coordinator. It was suggested that some one from the men's ministry or ushers group could fill this position.

If we used the fifty parking space in front of the church, someone would have to control the area. Certainly the winter and snow problems will become the most difficult aspect of a front parking area.